

Appendix B6. Photographic Log of Pre-construction Dewatering Monitoring on April 28, 2014

Monitoring Location M1



Photograph 1. ↑
Pond and surrounding vegetation, facing west.



Photograph 2. ↑
Algae present in east end of pond.



Photograph 3. ↑
Manitoba Maple (*Acer negundo*)
trees surrounding pond.



Photograph 4. ↑
Location of culvert on east side of pond.